

Auto Preparation Tool

AP-F38

Prep tool - N-type Connector only for CS-F38P 3/8-inch Coax cable

- Stripping and Coring tool for 3/8-inch coaxial cable
- Manual or Drill Operation
- High Quality of Anodized Aluminum
- Multiple blades for stripping and coring




Mechanical Specifications

Body Material	Anodized Aluminum
Tool	Automated cable Prep tool
Supporting Coaxial Cable	CS-F38P 3/8" coax only
Related Connectors	CN-NM-F38 (N-type male) CN-NF-F38 (N-type female)
Dimension (in/mm)	1.57x1.57x4.72/ 40.0x40.0x120.0
Weight (lb./kg)	0.46 / 0.21
Shipping Dimension (in/mm)	4.92x3.35x3.35 / 125.0x85.0x85.0
Shipping Weight (lb./kg)	0.60 / 0.27


Outline Drawing

AP-F38 Preparation tool operation for stripping and coring

- Manual and drill operation.
- Please cut the cable as clean as possible. Especially center conductor.



Step 1. Please cut cable as clean as possible.
The cutting edge is to be at the top of corrugation



Step 2. Please use auto prep tool, AP-F38 and remove all remaining dielectric material after using auto prep tool

- After stripping/coring and final assembly with CN-NM-F38(N-type connector)

